Installation Instructions

Preamplifier Update - KIT #26685202, 26685203

This kit will upgrade your AMI NGX preamplifier providing improved performance.

- Better bass response
- Cleaner, clearer music playback
- Improved volume control when separating zones 1 & 2 or zones 3 & 4

Parts Included with this Kit

Item	Kit 26685202	Kit 26685203	Description	Quanity
	Part Number	Part Number	Description	
1	70039192		Microprocessor V3.225	1
		70039193	Microprocessor V3.325	1
2	70039194	70039194	EEPROM V1.025	1

Compare the parameters in the table below to determine which kit is required. Firmware versions can be found on the part labels for U22 and U9 or by looking at the Hardware Information screen under Diagnostics in Service Mode. The firmware versions are displayed in the AMP text box.

Preamplifier Part Number	Processor Part Number	Firmware Version	Use Kit:
61200706 Rev D – Rev I	70039174	V3.1xx, or V3.2xx	26685202
61200707	70039188	V3.3xx	26685203

- 1. Turn off the jukebox and unplug the power cord. Open the jukebox and remove the amplifier assembly.
- 2. Remove two screws to open the amplifier. Identify the locations of the microprocessor U22 and the EEPROM U9. Note their pin 1 positions.
- 3. Using proper anti-static practice, carefully remove U22 and U9 from their sockets. Install the new microprocessor and EEPOM from the kit paying specific attention to pin 1 orientation.
- 4. Reassembly the amplifier, reinstall in the jukebox. Power up the jukebox and test by playing a music selection.



